



Pilot holes show also saturated all the way to the stern although no visible cracks on underside of hull



crack on underside



sanded down and wet foam removed



crack on underside

