

Optrel Welding Helmets Page 1

For more information, call Western Safety Products at 206-264-0808 or email sales@westernsafety.com.
We accept VISA and Mastercharge.

Optrel Galaxy Welding Helmet



The Optrel Galaxy features a modular viewing adapter that can be easily swapped in and out to provide multiple viewing options. The adapters' viewing ranges are available in a choice of 2" X 4-1/4" stationary or flip-up, 90 mm X 110 mm, or 4" X 5-1/4" sizes. They are precisely engineered to provide a snug, no slip fit as well as ease of replacement. Buy the revolutionary Galaxy complete with any size viewing adapter or any of the adapters separately and swap them in and out for your viewing preference. Maximum flexibility with minimum adjustment.


Mission critical equipment for welders. The Optrel Galaxy's tilting and telescoping headgear allows adjustment of the helmet position from the face and chin. The futuristic and sleek helmet design provides extended coverage of the chest, ear and head regions from harmful spatter and fumes.



Optrel Satellite Welding Helmet



The Optrel Satellite is more than a helmet. It is a command center for welders. No longer are you confined to a boxy welding helmet. The futuristic and sleek Satellite helmet has set a new standard by which all helmets will be measured. Take control of your productivity by only removing your helmet when you want to. In combination with Optrel's proven auto darkening filter (ADF) technology, the Satellite's easily accessible external controls not only eliminate the need for helmet removal, they make all other methods extinct. The multifunctional injection molded spherical cover lens not only reduces reflection, thus providing better visibility and optics, but its foam gasket ensures the protection of the ADF by sealing out harmful dust, spatter and moisture particles. The lens is molded thicker to resist heat warping during high amp welding.



Controls for helmet as shown schematically above.

1. Grinding:

Simply press the oversized shade control button and the auto darkening filter is locked in to a shade 4. This eliminates filter flickering while grinding or brazing. Both are now possible without helmet removal. Depress control button again to reset ADF

2. Shade Range Selection:

This sliding switch can be used to select shade ranges of 5 - 9 and 9 - 13. Choose your range and then adjust to the appropriate shade using the shade level control knob

WSP home	Products	Suppliers
Eye Protection	UVEX	