




VpCI® EMITTING SYSTEMS & ELECTRONIC PRODUCTS

CASE HISTORY

VpCI®-105, VpCI®-111 & ElectriCorr® VpCI®-239



DATE

November 19, 1999

CUSTOMER

Fisher Implement Co.

CORTEC REP

Alpine Summit

LOCATION

Albany, OR

CORTEC PRODUCTS

VpCI®-105
VpCI®-111
ElectriCorr® VpCI®-239

PROBLEM

The Fisher Implement Company suffered from corrosion on the controller contacts of their field irrigation equipment. The corrosion caused machine failures and equipment down time.

APPLICATION

Fisher Implement Co. used Cortec products to solve the corrosion problem. ElectriCorr® VpCI®-239 cleaned and protected the contacts on the irrigation equipment. Cortec® VpCI®-105 and VpCI®-111 emitters were placed inside the control boxes for long term protection.

CONCLUSION

By using Cortec® products, Fisher Implement Co. solved their corrosion problem. Fisher was also pleased with the environmentally friendly feature of Cortec's products.